

## Notices of Violation Issued January 2015

[illegible]

### Penalty Settlement Payments Received January 2015

Nov #	Facility	Location	Source Of Violation	Violation Issued	Rule	Date Paid	Total Penalty Received
10596	Bardex Corporation	Goleta	Used non-compliant cleaning solvent	9/22/2014	330	01/05/2015	\$500
10539	Blosser, 1611 S. (MVFF) - NAPHT LLC (ARCO)	Santa Maria	Failed to maintain equipment as certified by ARB	8/25/2014	206	01/12/2015	\$250
10540	Blosser, 1611 S. (MVFF) - NAPHT LLC (ARCO)	Santa Maria	Failed to maintain equipment as certified by ARB	8/25/2014	316	01/12/2015	\$250
10700	Forms and Surfaces Company, Inc.	Carpinteria	Used non-compliant cleaning solvent	10/1/2014	353	01/12/2015	\$500
10681	Platform Hermosa - Freeport-McMoRan Oil & Gas, LLC.	OCS	Exceeded mass emission & hydrogen sulfide limits	12/3/2014	206	01/12/2015	\$1,000
10704	Ellwood Onshore Facility - Venoco	Goleta	Conducted unplanned flaring	10/13/2014	206	01/13/2015	\$750
10674	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded mass emission limits	10/17/2014	206	01/13/2015	\$250
10554	Federal Aviation Admin.- SBAA RTR	Goleta	Failed to submit Annual Report	6/23/2014	206	01/21/2015	\$250
10555	Federal Aviation Administration - Santa Barbara Airport	Goleta	Operated equipment without benefit of PTO	6/23/2014	201	01/21/2015	\$500
10675	Las Flores Canyon - ExxonMobil Production Company	Goleta	Failed to operate vapor recovery equipment	12/3/2014	206	01/23/2015	\$1,000
10678	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded mass emission limits	12/3/2014	206	01/23/2015	\$20,000
10679	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded mass emission limits	12/3/2014	206	01/23/2015	\$10,500
10680	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded mass emission limits	12/3/2014	206	01/23/2015	\$1,000
10684	Las Flores Canyon - ExxonMobil Production Company	Goleta	Visible emissions present during flaring	12/3/2014	206	01/23/2015	\$1,000
10685	Platform Heritage - ExxonMobil Production Company	OCS	Operated equipment prior to authorization	12/4/2014	202	01/23/2015	\$500
10546	La Purisima Golf Course	Lompoc	Failure to comply with vapor recovery requirements	10/10/2014	206	01/26/2015	\$500

**\$38,750**